

Background:

When action 09-794 was developed, the focus was on developing Class 2 and Class 3 Acceptance Criteria as part of the Operational Leakage action. During development of Record 09-794, the committee failed to make a change to IWA-5250(a)(1) regarding the reference to the Class 3 Acceptance Standard.

Prior to the 2013 Edition, Class 2 and Class 3 Acceptance criteria was in the course of preparation, therefore the applicability should be 2013 Edition through the 2017 Edition.

This action is considered to be an Editorial Action.

IWA-5250 CORRECTIVE ACTION

(a) The sources of leakage detected during the conduct of a system pressure test shall be located and evaluated by the Owner for corrective action as follows:

(1) Buried components with leakage losses in excess of limits acceptable for continued service shall meet the requirements of [IWB-3142](#), [IWC-3132](#), or ~~[IWD-3120](#)~~, as applicable.



IWD-3132