

Errata to ASME B30.26-2010 Rigging Hardware

The errata correction listed below applies to ASME B30.26-2010. See overleaf for revised figure.

<i>Page</i>	<i>Location</i>	<i>Change</i>
9	Fig. 26-2.1.1-2	Values of "Vertical Angle" and "% of Rated Load" were added above "Angular Loading" beneath the fourth illustration

THE AMERICAN SOCIETY OF MECHANICAL ENGINEERS
Three Park Avenue, New York, NY 10016-5990

January 2011



J1700E

Fig. 26-2.1.1-2 Eyebolts

